
City of Baltimore Wet Smoke and Dyed	Page 1 of 2	
Sewershed: Gwynns Falls	Company: Savin	Date: 4/21/2009
Test to be performed: Smoke Dyed Water X	Ground Condition: Dry ☑ Damp ☐ Wet ☐	Supervisor: <u>JAW</u>
Manhole_ID: S05KK1018MH	Test ID: <u>D1032-034020</u>	Notification Made: NA (Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Water Level	
0			Manhole	S05KK1018MH
0			Start of Survey	
29.39999962			Joint Offset Medium	
37.29999924	02		Tap Factory Defective	JOM
37.29999924	02		Infil Runner	JOINT IN TAP 1 GPM
40.5			Joint Offset Medium	
101.0999985			Dye Test Visible	@ IR, 0.5gpm
103.9000015	01		Tap Break-in Intruding	
104.3000031			Joint Offset Medium	
107.3000031			Dye Test Visible	@ IG, 1.25gpm

City of Baltimore Wet Smoke and Dyed	Page 2 of 2	
Sewershed: Gwynns Falls	Company: Savin	Date: 4/21/2009
Test to be performed: Smoke Dyed Water X	Ground Condition: Dry ✓ Damp ☐ Wet ☐	Supervisor: <u>JAW</u>
Manhole_ID: S05KK1018MH	Test ID: <u>D1032-034020</u>	Notification Made: NA (Residents, Fire, 311)
113	Abandoned Survey DYE FLO	OOD COMPLETED